

## 2002 TrailBlazer SWB

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 050601026                      Date of Bulletin: SEP 01, 2005  
NHTSA Item Number: 10017818  
Component: ENGINE AND ENGINE COOLING

Summary:  
INFORMATION ON USE OF BOLT EXTRACTOR TOOL KIT PART NUMBER EN-47702 FOR REMOVING BROKEN CYLINDER HEAD OR MAIN BEARING CAP BOLTS ON INLINE TRUCK ENGINES. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 050235006                      Date of Bulletin: AUG 01, 2005  
NHTSA Item Number: 10017371  
Component: STEERING

Summary:  
HISS/RUSH NOISE FROM STEERING (STRG) COLUMN AREA. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 050730021                      Date of Bulletin: AUG 01, 2005  
NHTSA Item Number: 10017381  
Component: ELECTRICAL SYSTEM:IGNITION:SWITCH

Summary:  
IGNITION KEY WILL NOT REMOVE FROM IGNITION LOCK CYLINDER. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 020730024A                      Date of Bulletin: AUG 01, 2005  
NHTSA Item Number: 634999  
Component: POWER TRAIN:AUTOMATIC TRANSMISSION:LEVER AND LINKAGE:COLUMN SHIFT

Summary:  
DIAGNOSIS OF CRACKED OR BROKEN TRANSMISSION CASE. \*TT 2006 AND PRIOR CARS AND LIGHT DUTY TRUCKS. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 030523002                      Date of Bulletin: MAY 01, 2005  
NHTSA Item Number: 10017359  
Component: SERVICE BRAKES, HYDRAULIC:FOUNDATION COMPONENTS:DISC:CALIPER

Summary:

## For TrailVoy.com Members Only

REVISED FRONT BRAKE CALIPER BRACKET MOUNTING BOLT FASTENER TIGHTENING SPECIFICATION. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 20050577                      Date of Bulletin: APR 14, 2005  
NHTSA Item Number: 10014969  
Component: FUEL SYSTEM, GASOLINE:STORAGE:TANK ASSEMBLY  
Summary:  
    FUEL TANK INLET CHECK VALVE FRACTURE. \*EH

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 0508110004                      Date of Bulletin: APR 01, 2005  
NHTSA Item Number: 10017326  
Component: STRUCTURE:BODY  
Summary:  
    CARGO COVER HANDLE BROKEN. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 050308007                      Date of Bulletin: APR 01, 2005  
NHTSA Item Number: 10017342  
Component: SUSPENSION  
Summary:  
    RATTLE, CLUNK, POP, SNAP NOISE FROM FRONT AND/OR REAR SUSPENSION WHILE DRIVING OVER  
    ROUGH, UNEVEN, WASH BOARD ROAD SURFACES. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 1363                      Date of Bulletin: MAR 14, 2005  
NHTSA Item Number: 10015049  
Component: FUEL SYSTEM, GASOLINE:STORAGE:AUXILLARY TANK  
Summary:  
    FUEL TANK INLET CHECK VALVE FRACTURE. \*EH

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 040525002A                      Date of Bulletin: MAR 01, 2005  
NHTSA Item Number: 10008659  
Component: SERVICE BRAKES, HYDRAULIC:ANTILOCK:CONTROL UNIT/MODULE  
Summary:  
    ANTI-LOCK BRAKE SYSTEM (ABS) LIGHT ON, DIAGNOSTIC TROUBLE CODES (DTCS) C0265, C0201, U1041 SET  
    AND/OR LOSS OF COMMUNICATION WITH BRAKE MODULE. \*TT UPDATE. \*TT

For TrailVoy.com Members Only

**For TrailVoy.com Members Only**

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 050604014                      Date of Bulletin: MAR 01, 2005  
NHTSA Item Number: 10014993  
Component: ENGINE AND ENGINE COOLING:EXHAUST SYSTEM:EMISSION CONTROL

Summary:  
DIAGNOSTIC AIDS FOR DIAGNOSTIC TROUBLE CODES P0440, P0455 AND/OR P0442 - EVAPORATIVE EMISSION (EVAP) SYSTEM LEAK. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 050842001                      Date of Bulletin: MAR 01, 2005  
NHTSA Item Number: 10015012  
Component: EXTERIOR LIGHTING:HEADLIGHTS

Summary:  
DIAGNOSTIC INFORMATION ON HEADLAMPS FLICKER OR MOMENTARILY DIM WHILE DRIVING. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 702                      Date of Bulletin: FEB 01, 2005  
NHTSA Item Number: 10016372  
Component: STRUCTURE:BODY:HATCHBACK/LIFTGATE:HINGE AND ATTACHMENTS

Summary:  
UNLOCKING LIFTGATE LATCH. GM TECH LINKS. 2002 AND NEWER CHEVROL TRAILBLAZER, GMC ENVOY, OLDSMOBILE BRAVADA AND BUICK RAINER. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 030857004                      Date of Bulletin: JAN 01, 2005  
NHTSA Item Number: 10004735  
Component: STRUCTURE:BODY

Summary:  
WET FRONT FLOOR CARPET. \*TT UPDATE. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 020526001B                      Date of Bulletin: JAN 01, 2005  
NHTSA Item Number: 10006115  
Component: PARKING BRAKE

Summary:  
REAR PARKING BRAKE SHOE RETAINING SPRING CLIP SERVICE KIT FOR DRUM-IN-HAT (DIH) EQUIPPED VEHICLES. \*TT UPDATE. \*TT

---

**For TrailVoy.com Members Only**

**For TrailVoy.com Members Only**

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 050138001                      Date of Bulletin: JAN 01, 2005  
NHTSA Item Number: 10013447  
Component: EQUIPMENT:OTHER:OWNERS/SERVICE/OTHER MANUAL

Summary:  
NEW ESSENTIAL TOOL FOR HVAC MODE DOOR ACTUATOR REPLACEMENT. \*EH

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 020309002B                      Date of Bulletin: DEC 01, 2004  
NHTSA Item Number: 10005147  
Component: SUSPENSION

Summary:  
INTERMITTENT BOOM, RUMBLING NOISE AND / OR DISTURBANCE HEARD IN PASSENGER COMPARTMENT WHILE DRIVING AT HIGHWAY SPEEDS. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 030235006                      Date of Bulletin: DEC 01, 2004  
NHTSA Item Number: 10005165  
Component: STEERING

Summary:  
REVISED STEERING WHEEL REPLACEMENT PROCEDURE. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 3152                      Date of Bulletin: DEC 01, 2004  
NHTSA Item Number: 10009989  
Component: EQUIPMENT:ELECTRICAL:AIR CONDITIONER

Summary:  
BLOWER SPEED CHANGES ON ITS OWN. \*TC UPDATE. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 040421004                      Date of Bulletin: DEC 01, 2004  
NHTSA Item Number: 10017442  
Component: POWER TRAIN:TRANSFER CASE (4-WHEEL DRIVE)

Summary:  
4WD SWITCH INDICATOR LIGHTS FLASHING, 4WD INOPERATIVE, DIAGNOSTIC TROUBLE CODES C0327, P0550 SET. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002

**For TrailVoy.com Members Only**

**For TrailVoy.com Members Only**

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 04087

Date of Bulletin: NOV 16, 2004

NHTSA Item Number: 10011954

Component: EXTERIOR LIGHTING

Summary:

TAIL LAMPS/STOP LAMPS PRODUCT FIELD ACTION ANNOUNCEMENT. \*TT ADMINISTRATIVE MESSAGE. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 04087

Date of Bulletin: NOV 01, 2004

NHTSA Item Number: 10014003

Component: EXTERIOR LIGHTING:TAIL LIGHTS

Summary:

TAIL LAMP THAT MAY BECOME INOPERATIVE PREMATURELY. \*EH

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 0308111002A

Date of Bulletin: OCT 01, 2004

NHTSA Item Number: 10005189

Component: STRUCTURE:BODY

Summary:

PAINT CHIPPING BEHIND FRONT WHEELS/FRONT OF REAR WHEELS, DAMAGED LOWER DOOR/CLADDING AND ROCKER PANELS. \*TT THIS SERVICE BULLETIN REPLACES 0308111002. \*EH UPDATE. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 030601028A

Date of Bulletin: OCT 01, 2004

NHTSA Item Number: 10005558

Component: ENGINE AND ENGINE COOLING:ENGINE

Summary:

INFORMATION ON CORRECT PISTON USAGE. \*TT UPDATED \*EH

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 030940006A

Date of Bulletin: OCT 01, 2004

NHTSA Item Number: 10005592

Component: SEAT BELTS:FRONT:RETRACTOR

Summary:

INFORMATION ON AVOIDING FRONT SEAT BELT RETRACTOR JAMMING WHEN STORING SEAT BELT. \*TT UPDATED \*EH

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

**For TrailVoy.com Members Only**

**For TrailVoy.com Members Only**

Service Bulletin Num : 040866001

Date of Bulletin: OCT 01, 2004

NHTSA Item Number: 10011141

Component: STRUCTURE:BODY

Summary:

REAR LICENSE PLATE POCKET GASKET LOOSE OR OUT OF POSITION. \*TT UPDATE. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 04017A

Date of Bulletin: SEP 29, 2004

NHTSA Item Number: 10010181

Component: EXTERIOR LIGHTING:TAIL LIGHTS

Summary:

TAIL LAMP/STOP LAMP(S) MAY BECOME INOPERATIVE. GM ADMINISTRATIVE MESSAGE. \*NM

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 030419002

Date of Bulletin: SEP 01, 2004

NHTSA Item Number: 10001123

Component: POWER TRAIN:AXLE ASSEMBLY

Summary:

SQUEAK, SQUEAL OR WHISTLE NOISE FROM FRONT AXLE. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 010866007

Date of Bulletin: SEP 01, 2004

NHTSA Item Number: 10010430

Component: INTERIOR LIGHTING

Summary:

CENTER HIGH-MOUNT STOP LAMP (CHMSL) APPLIQUE LOOSE. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 040845010

Date of Bulletin: SEP 01, 2004

NHTSA Item Number: 10011074

Component: ELECTRICAL SYSTEM

Summary:

VARIOUS INTERIOR ELECTRICAL CONCERNS, IP GAUGES/LIGHTING INOPERATIVE, HVAC CONTROLS INOPERATIVE, BLOWER MOTOR INOPERATIVE, RADIO INOPERATIVE, FLASHER INOPERATIVE. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 040864012

Date of Bulletin: SEP 01, 2004

**For TrailVoy.com Members Only**

**For TrailVoy.com Members Only**

NHTSA Item Number: 10011083

Component: STRUCTURE:BODY

Summary:

FRONT OR REAR SIDE DOOR GLASS SCRATCHED. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 04017

Date of Bulletin: AUG 05, 2004

NHTSA Item Number: 10007440

Component: EXTERIOR LIGHTING:TAIL LIGHTS

Summary:

SPECIAL POLICY ADJUSTMENT - TAIL LAMP/STOP LAMP INOPERATIVE. ANSWERS TO ASSIST IN RESPONDING TO CUSTOMER INQUIRIES. \*MJ THIS IS THE FIRST PHASE WHICH WAS RELEASED JUNE 3, 2004. \*TT THIS IS THE SECOND PHASE - PHASE II. \*TT PHASE III. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 030864006

Date of Bulletin: AUG 01, 2004

NHTSA Item Number: 10001264

Component: STRUCTURE:BODY:DOOR

Summary:

DOORS HARD TO CLOSE. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 04017A

Date of Bulletin: AUG 01, 2004

NHTSA Item Number: 10009630

Component: EXTERIOR LIGHTING

Summary:

TAIL LAMPS/STOP LAMPS. SPECIAL POLICY SERVICE BULLETIN. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 040602005

Date of Bulletin: AUG 01, 2004

NHTSA Item Number: 10011205

Component: ENGINE AND ENGINE COOLING:ENGINE

Summary:

HIGHER THAN NORMAL ENGINE COOLANT TEMPERATURE GAUGE READINGS. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 040604003

Date of Bulletin: AUG 01, 2004

NHTSA Item Number: 10011209

**For TrailVoy.com Members Only**

**For TrailVoy.com Members Only**

Component: FUEL SYSTEM,GASOLINE:STORAGE:TANK ASSEMBLY

Summary:

VEHICLE IS DIFFICULT TO FILL WITH FUEL OR FILLING STATION PUMP SHUTS OFF BEFORE TANK IS FULL OR FUEL SPITS BACK/OUT WHEN FILLING TANK. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 040730035

Date of Bulletin: AUG 01, 2004

NHTSA Item Number: 10011217

Component: POWER TRAIN:AUTOMATIC TRANSMISSION

Summary:

RELEASE OF REAR TRANSMISSION MOUNT SEPARATE FROM EXHAUST MOUNT. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 040843007

Date of Bulletin: AUG 01, 2004

NHTSA Item Number: 10011226

Component: VISIBILITY:REAR WINDOW WIPER/WASHER

Summary:

REAR WIPER DOES NOT CLEAN REAR WINDOW. \*EH

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 020139007

Date of Bulletin: AUG 01, 2004

NHTSA Item Number: 10011227

Component: OTHER

Summary:

AUTOMATIC DUAL ZONE HVAC BATTERY DRAW. \*AR

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 07082004

Date of Bulletin: JUL 08, 2004

NHTSA Item Number: 10013185

Component: ENGINE AND ENGINE COOLING

Summary:

HIGHER THAN PERCEIVED NORMAL ENGINE COOLANT TEMPERATURE GAUGE READINGS WHEN OPERATING THE VEHICLE IN VERY HIGH OUTSIDE AMBIENT TEMPERATURES AND IN STOP AND GO OR SLOW MOVING TRAFFIC CONDITIONS. \*EH

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 07062004

Date of Bulletin: JUL 06, 2004

NHTSA Item Number: 10013180

**For TrailVoy.com Members Only**



**For TrailVoy.com Members Only**

Component: VISIBILITY:WINDSHIELD WIPER/WASHER:MOTOR

Summary:

WATER SEEP INTO THE WINDSHIELD WIPER MODULE. \*EH

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 040601022

Date of Bulletin: JUL 01, 2004

NHTSA Item Number: 10012109

Component: ENGINE AND ENGINE COOLING:ENGINE

Summary:

NEW CYLINDER BORE LINER/PISTON SLEEVE REPLACEMENT PROCEDURE. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 07012004

Date of Bulletin: JUL 01, 2004

NHTSA Item Number: 10014251

Component: EQUIPMENT:OTHER:OWNERS/SERVICE/OTHER MANUAL

Summary:

OIL LIFE SYSTEM RESET PROCEDURES-TRUCKS. BUICK TERAZZA 2005, GMC SIERRA DENALI 2002-2003, GMC B7 CHASSIS MEDIUM DUTY 2003-2005 AND GMC 560 C-SERIES 2003-2005 \*SC

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 030604030

Date of Bulletin: JUN 01, 2004

NHTSA Item Number: 10002166

Component: ENGINE AND ENGINE COOLING:ENGINE

Summary:

MULTIPLE DRIVEABILITY SYMPTOMS OF LONG OR HARD STARTS, CHUGGLE, ROUGH IDLE AND LIGHT OR INTERMITTENT MISFIRE DUE TO CLOGGED FUEL INJECTORS. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 030842006A

Date of Bulletin: JUN 01, 2004

NHTSA Item Number: 10004774

Component: EXTERIOR LIGHTING:TAIL LIGHTS:SWITCH

Summary:

TAIL LAMP CIRCUIT BOARD NOW AVAILABLE FOR SERVICE USE. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 020862004

Date of Bulletin: JUN 01, 2004

NHTSA Item Number: 10012157

Component: STRUCTURE:BODY

**For TrailVoy.com Members Only**

## For TrailVoy.com Members Only

Summary:

FRONT FASCIA WAVY. THIS SERVICE BULLETIN REPLACES 020862004. \*EH

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 040863005                      Date of Bulletin: JUN 01, 2004  
NHTSA Item Number: 10012537  
Component: STRUCTURE:BODY:HOOD

Summary:

RATTLE NOISE UNDER HOOD. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 040866004                      Date of Bulletin: JUN 01, 2004  
NHTSA Item Number: 10012538  
Component: STRUCTURE:BODY:HATCHBACK/LIFTGATE:HINGE AND ATTACHMENTS

Summary:

LIFTGATE GLASS UNLATCHES ON ROUGH/BUMPY ROAD SURFACES. THIS BULLETIN REPLACES PREVIOUS BULLETIN NUMBER 04-08-66-004. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 0408111003                      Date of Bulletin: JUN 01, 2004  
NHTSA Item Number: 10012546  
Component: STRUCTURE:BODY

Summary:

REAR LICENSE PLATE POCKET PARTS NEW AVAILABLE INDIVIDUALLY. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 010604052A                      Date of Bulletin: MAY 01, 2004  
NHTSA Item Number: 10005146  
Component: ENGINE AND ENGINE COOLING:ENGINE

Summary:

ON-BOARD DIAGNOSTIC (OBD) SYSTEM IMPROVEMENTS - SERVICE ENGINE SOON LIGHT ON, DIAGNOSTIC TROUBLE CODE (DTC) P0014, P0116, OR P1683 SET, DELAYED TRANSMISSION DOWNSHIFT AND/OR EXCESSIVE FAN NOISE. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 040601015                      Date of Bulletin: MAY 01, 2004  
NHTSA Item Number: 10008501  
Component: ENGINE AND ENGINE COOLING:ENGINE

**For TrailVoy.com Members Only**

Summary:

NEW DESIGN OIL PICK UP TUBE AND FRONT COVER. \*MJ

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 040421001

Date of Bulletin: MAY 01, 2004

NHTSA Item Number: 10008503

Component: POWER TRAIN:DRIVELINE

Summary:

DELAYED ENGAGEMENT OF FRONT WHEELS DURING A SLIP CONDITION. \*MJ

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 040603005

Date of Bulletin: APR 01, 2004

NHTSA Item Number: 10008665

Component: ELECTRICAL SYSTEM

Summary:

PROPER CONNECTION INFORMATION TO AVOID BLOWN 125 AMP FUSE AND VARIOUS INTERIOR ELECTRICAL SYSTEM CONDITIONS WHEN JUMP STARTING VEHICLE. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 040523003

Date of Bulletin: APR 01, 2004

NHTSA Item Number: 10012585

Component: SERVICE BRAKES, AIR:DISC:CALIPER

Summary:

REVISED REAR BRAKE CALIPER BRACKET MOUNTING BOLT FASTENER SPECIFICATION. \*EH

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 020421006C

Date of Bulletin: MAR 01, 2004

NHTSA Item Number: 10004357

Component: POWER TRAIN:TRANSFER CASE (4-WHEEL DRIVE)

Summary:

INOPERATIVE 4WD/AWD LAMPS, INOPERATIVE 4WD/AWD SYSTEM. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 040139002

Date of Bulletin: MAR 01, 2004

NHTSA Item Number: 10008648

Component: EQUIPMENT:ELECTRICAL

Summary:

POOR HEATER PERFORMANCE - 2ND AND 3RD ROW SEATS. \*TT

**For TrailVoy.com Members Only**

**For TrailVoy.com Members Only**

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 040232001                      Date of Bulletin: MAR 01, 2004  
NHTSA Item Number: 10012694  
Component: STEERING  
Summary:  
RELEASE OF STEERING GEAR STUB SHAFT BEARING KIT FOR SERVICE. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 02122004                      Date of Bulletin: FEB 12, 2004  
NHTSA Item Number: 10012992  
Component: EQUIPMENT:ELECTRICAL:AIR CONDITIONER  
Summary:  
INADEQUATE HVAC FOR PASSENGERS SEATED IN THE SECOND AND THIRD ROW. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 02112004                      Date of Bulletin: FEB 11, 2004  
NHTSA Item Number: 10012989  
Component: VISIBILITY:WINDSHIELD WIPER/WASHER  
Summary:  
WATER CAN ENTER THE WINDSHIELD WIPER MODULE CAUSING A SHORT CIRCUIT OR CORROSION OF COMPONENTS WHILE IN USE. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 040603002                      Date of Bulletin: FEB 01, 2004  
NHTSA Item Number: 10012703  
Component: ENGINE AND ENGINE COOLING  
Summary:  
DIAGNOSTIC INFORMATION FOR INTERMITTENT VEHICLE NO CRANK DEAD BATTERY. \*EH

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 00078F                      Date of Bulletin: JAN 01, 2004  
NHTSA Item Number: 10004246  
Component: ENGINE AND ENGINE COOLING:ENGINE  
Summary:  
ENGINE KNOCK NOISE INITIAL STARTUP IN COLD AMBIENT 10 DEGREES CENTIGRADE/50 DEGREES FAHRENHEIT. \*TT

---



**For TrailVoy.com Members Only**

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 00822B

Date of Bulletin: JAN 01, 2004

NHTSA Item Number: 10005474

Component: POWER TRAIN

Summary:

NO 2ND, NO 4TH AND NO REVERSE. TO INCLUDE 2004 LIGHT DUTY AUTOMOBILES AND TRUCKS EQUIPPED WITH 4L60E OR 4L65E AUTOMATIC TRANSMISSION. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 00702

Date of Bulletin: JAN 01, 2004

NHTSA Item Number: 10005476

Component: POWER TRAIN:AUTOMATIC TRANSMISSION

Summary:

SLIP CONDITION IN 2ND, 3RD OR 4TH DAMAGED 2-4 BAND 3-4 CLUTCH ON THE 4L60E/4L65E AUTOMATIC TRANSMISSION. \*TT \*MJ

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 01764

Date of Bulletin: JAN 01, 2004

NHTSA Item Number: 10006261

Component: FUEL SYSTEM, GASOLINE

Summary:

VEHICLE DIFFICULT TO FILL WITH FUEL/ FILLING STATION PUMP SHUTS OFF BEFORE TANK FULL. ALSO INCLUDING 2003 BUICK RAINIER. \*MR

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 01663A

Date of Bulletin: JAN 01, 2004

NHTSA Item Number: 10006296

Component: STRUCTURE

Summary:

VIBRATION NOISE FROM UNDER HOOD, SOUNDS LIKE SHEET METAL VIBRATING. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 01900

Date of Bulletin: JAN 01, 2004

NHTSA Item Number: 10006472

Component: ELECTRICAL SYSTEM:FUSES AND CIRCUIT BREAKERS

Summary:

UNDER HOOD FUSE BLOCK - 125 AMP MEGA FUSE BLOWN. ALSO INCLUDING BUICK RAINIER 2002, 2003. \*MR

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

**For TrailVoy.com Members Only**

**For TrailVoy.com Members Only**

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 01925

Date of Bulletin: JAN 01, 2004

NHTSA Item Number: 10006566

Component: ELECTRICAL SYSTEM

Summary:

TECH 2 ENGINE DATA INCORRECT- GEN L-TERMINAL SIGNAL COMMAND DATA PARAMETER. \*MR

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 01816

Date of Bulletin: JAN 01, 2004

NHTSA Item Number: 10006670

Component: ELECTRICAL SYSTEM

Summary:

DIAGNOSTIC TROUBLE CODE P0130. \*MR \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 02038

Date of Bulletin: JAN 01, 2004

NHTSA Item Number: 10006946

Component: ELECTRICAL SYSTEM

Summary:

DIAGNOSTIC TROUBLE CODE B1000. \*MR

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 01623

Date of Bulletin: JAN 01, 2004

NHTSA Item Number: 10007186

Component: ELECTRICAL SYSTEM

Summary:

4.2 LL8 ENGINE DIAGNOSTIC TROUBLE CODE P0016 OR P1345 WITH NO DRIVEABILITY SYMPTOMS.\*MR

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 01676

Date of Bulletin: JAN 01, 2004

NHTSA Item Number: 10007188

Component: ENGINE AND ENGINE COOLING:COOLING SYSTEM:FAN

Summary:

4.2 4L60E ENGINE COOLING FAN CONTACTS SHROUD AFTER REPLACING RADIATOR. \*MR

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 01673

Date of Bulletin: JAN 01, 2004

**For TrailVoy.com Members Only**

**For TrailVoy.com Members Only**

NHTSA Item Number: 10007192

Component: ELECTRICAL SYSTEM

Summary:

DIAGNOSTIC TROUBLE CODES P1271, P1275 LOW POWER.\*MR

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 02023

Date of Bulletin: JAN 01, 2004

NHTSA Item Number: 10007212

Component: ENGINE AND ENGINE COOLING:ENGINE

Summary:

INTERMITTENT NO CRANK NO START. SECURITY LIGHT MAY BE ON OR OFF. 4.2 LL8 ENGINE. \*NM

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 01599

Date of Bulletin: JAN 01, 2004

NHTSA Item Number: 10007237

Component: POWER TRAIN

Summary:

4L60E, 4L65E FORWARD AND LOW REVERSE WAVED STEEL CLUTCH PLATE APPEARANCE CHANGE. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 01672

Date of Bulletin: JAN 01, 2004

NHTSA Item Number: 10007247

Component: ENGINE AND ENGINE COOLING:ENGINE

Summary:

OIL PAN DRAIN PLUG THREADS - INFORMATION. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 01115A

Date of Bulletin: JAN 01, 2004

NHTSA Item Number: 10007273

Component: SUSPENSION

Summary:

CLUNK, RATTLE NOISE FROM FRONT OF VEHICLE OVER BUMPS. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 01968A

Date of Bulletin: JAN 01, 2004

NHTSA Item Number: 10007277

Component: ELECTRICAL SYSTEM

**For TrailVoy.com Members Only**



## For TrailVoy.com Members Only

Summary:

DIAGNOSTIC TROUBLE CODE (DTC) P0171. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 00859

Date of Bulletin: JAN 01, 2004

NHTSA Item Number: 10007281

Component: ELECTRICAL SYSTEM

Summary:

DIAGNOSTIC TROUBLE CODE (DTC) C0327 WITH OR WITHOUT ADDITIONAL DIAGNOSTIC TROUBLE CODES (DTCS) SETTING. \*TT \*MJ

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 00372D

Date of Bulletin: JAN 01, 2004

NHTSA Item Number: 10007287

Component: EQUIPMENT:ELECTRICAL

Summary:

ONSTAR SYSTEM IS ATTEMPTING AND/OR COMPLETING PHONE CALLS WHICH THE OPERATOR OF THE VEHICLE DID NOT INITIATE. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 00949C

Date of Bulletin: JAN 01, 2004

NHTSA Item Number: 10007289

Component: STRUCTURE:BODY:HATCHBACK/LIFTGATE:HINGE AND ATTACHMENTS

Summary:

THE LIFTGATE OR LIFTGATE GLASS BINDS WHEN OPENING OR DOES NOT OPEN COMPLETELY BECAUSE THE CENTER HIGH MOUNTED STOP LAMP (CHMSL) APPLIQUE HITS THE ROOF OF THE VEHICLE. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 00686B

Date of Bulletin: JAN 01, 2004

NHTSA Item Number: 10007292

Component: EQUIPMENT:ELECTRICAL:RADIO/TAPE DECK/CD ETC.

Summary:

AUTOMATIC VOLUME FEATURE DIAGNOSIS ON THE UQA BOSE RADIO. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 02117

Date of Bulletin: JAN 01, 2004

NHTSA Item Number: 10007448

Component: POWER TRAIN

## For TrailVoy.com Members Only

Summary:

TCCM WILL NOT PROGRAM THROUGH TIS. \*MJ

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 01078E

Date of Bulletin: JAN 01, 2004

NHTSA Item Number: 10007552

Component: STRUCTURE

Summary:

NOISE FROM INSTRUMENT PANEL CLUSTER TACHOMETER. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 01016

Date of Bulletin: JAN 01, 2004

NHTSA Item Number: 10007572

Component: ELECTRICAL SYSTEM

Summary:

ANTI-LOCK BRAKE SYSTEM (ABS) LIGHT ON, RED BRAKE LIGHT ON, SERVICE 4WD LIGHT ON, HVAC BLOWER MOTOR INOPERATIVE. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 00731A

Date of Bulletin: JAN 01, 2004

NHTSA Item Number: 10007578

Component: STRUCTURE:BODY

Summary:

NOISE FROM FRONT OF VEHICLE OVER BUMPS OR UNDER LIGHT ACCELERATION. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 00156A

Date of Bulletin: JAN 01, 2004

NHTSA Item Number: 10007656

Component: ENGINE AND ENGINE COOLING:ENGINE

Summary:

4.2L LL8 ENGINE ROUGH IDLE - RUN POSSIBLE P1345 OR P0016. \*MJ \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 02053

Date of Bulletin: JAN 01, 2004

NHTSA Item Number: 10007739

Component: SERVICE BRAKES, HYDRAULIC

Summary:

INFORMATION ON RESURFACING THE PARK BRAKE PORTION OF THE REAR BRAKE ROTOR. \*TT



**For TrailVoy.com Members Only**

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 00877A

Date of Bulletin: JAN 01, 2004

NHTSA Item Number: 10007972

Component: SEATS:FRONT ASSEMBLY:SEAT HEATER/COOLER

Summary:

INTERMITTENT LACK OF HEAT IN 2ND AND 3RD ROW SEATING POSITIONS. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 3016

Date of Bulletin: JAN 01, 2004

NHTSA Item Number: 10008777

Component: ELECTRICAL SYSTEM

Summary:

VARIOUS ELECTRICAL CONCERNS. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 3002A

Date of Bulletin: JAN 01, 2004

NHTSA Item Number: 10008802

Component: POWER TRAIN

Summary:

4L60E/4L65E INTERMITTENT NEUTRAL CONDITION WHILE ACCELERATING FROM A STOP OR WHILE DRIVING. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 1528102

Date of Bulletin: JAN 01, 2004

NHTSA Item Number: 10008820

Component: ELECTRICAL SYSTEM

Summary:

02-04 4.2L LL8 DIAGNOSTIC TROUBLE CODE P0171. \*MJ

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 3011

Date of Bulletin: JAN 01, 2004

NHTSA Item Number: 10008898

Component: EQUIPMENT

Summary:

WHEN USING VOICE RECOGNITION DIALING, SOME NUMBERS OR COMMANDS MAY NOT BE UNDERSTOOD BY THE SYSTEM ESPECIALLY THE NUMBER TWO (2). \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

**For TrailVoy.com Members Only**

**For TrailVoy.com Members Only**

Service Bulletin Num : 3064

Date of Bulletin: JAN 01, 2004

NHTSA Item Number: 10009369

Component: SERVICE BRAKES, HYDRAULIC

Summary:

FRONT BRAKE NOISE OR SQUEALING ON THE FIRST FEW LIGHT BRAKE APPLIES AFTER THE VEHICLE HAS SAT FOR A LONG PERIOD OF TIME, SUCH AS OVERNIGHT. THIS MESSAGE APPLIES TO THE LONG WHEEL BASE MODEL. SERVICE VME. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 01012004

Date of Bulletin: JAN 01, 2004

NHTSA Item Number: 10009584

Component: ENGINE AND ENGINE COOLING

Summary:

HIGH COOLANT TEMPERATURE GAUGE READINGS DURING LOW RPM OPERATION. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 3052

Date of Bulletin: JAN 01, 2004

NHTSA Item Number: 10009592

Component: EQUIPMENT

Summary:

BREAKPOINTS FOR RELEASE 5 FOR THE F1 (GEN 5) EQUIPPED PRODUCTS. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 3047

Date of Bulletin: JAN 01, 2004

NHTSA Item Number: 10009607

Component: EQUIPMENT

Summary:

99 THROUGH 05 YEAR VEHICLES, EQUIPPED WITH THREE-BUTTON ONSTAR SYSTEMS. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 3042

Date of Bulletin: JAN 01, 2004

NHTSA Item Number: 10009642

Component: VEHICLE SPEED CONTROL:CRUISE CONTROL

Summary:

CRUISE CONTROL DISENGAGES AFTER ACCELERATING. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 3044

Date of Bulletin: JAN 01, 2004

**For TrailVoy.com Members Only**

**For TrailVoy.com Members Only**

NHTSA Item Number: 10009649

Component: EXTERIOR LIGHTING:HEADLIGHTS

Summary:

LOCATION OF THE HEADLAMP DRIVER MODULE (HDM). \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 3059

Date of Bulletin: JAN 01, 2004

NHTSA Item Number: 10009663

Component: SUSPENSION:FRONT

Summary:

RATTLE NOISE IN FRONT SUSPENSION OVER SMALL BUMPS, CLUNK OR LOOSE LUMBER TYPE NOISE OVER UNEVEN/WASH BOARD ROADS. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 3151

Date of Bulletin: JAN 01, 2004

NHTSA Item Number: 10009986

Component: VISIBILITY:REARVIEW MIRRORS/DEVICES:INTERIOR

Summary:

INSIDE REAR VIEW MIRROR DOES NOT DISPLAY AMBIENT TEMPERATURE WITH CJ2 OPTION. \*TC

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 3138

Date of Bulletin: JAN 01, 2004

NHTSA Item Number: 10010105

Component: ELECTRICAL SYSTEM

Summary:

REDUCED POWER LIGHT ON AND DIAGNOSTIC TROUBLE CODE P1680 P1221 AND/OR P1271 STORED IN THE POWER CONTROL MODULE. \*SC

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 3135

Date of Bulletin: JAN 01, 2004

NHTSA Item Number: 10010175

Component: STRUCTURE:BODY:HATCHBACK/LIFTGATE

Summary:

CHMSL APPLIQUE CONTACTS ROOF WHEN OPENING REAR GATE/GLASS. (TO INCLUDE 2005 CHEVROLET TRAILBLAZER) (MT 370 ONLY) \*SC

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 3124

Date of Bulletin: JAN 01, 2004

**For TrailVoy.com Members Only**

**For TrailVoy.com Members Only**

NHTSA Item Number: 10010188

Component: SUSPENSION

Summary:

UPPER AND LOWER INTERMEDIATE SHAFT PARTS RESTRICTION. \*SC

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 3116

Date of Bulletin: JAN 01, 2004

NHTSA Item Number: 10010189

Component: ELECTRICAL SYSTEM

Summary:

ENGINE STALLS WHEN AIR CONDITIONING IS TURNED ON AT IDLE. (TO INCLUDE 2005 CHEVROLET TRAILBLAZER, 2005 OLDSMOBILE BRAVADA, AND BUICK RAINIER) \*SC

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 3142

Date of Bulletin: JAN 01, 2004

NHTSA Item Number: 10010194

Component: ENGINE AND ENGINE COOLING:ENGINE

Summary:

BROKEN HEAD BOLT REPAIR. \*TC

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 3104

Date of Bulletin: JAN 01, 2004

NHTSA Item Number: 10010225

Component: EQUIPMENT:ELECTRICAL:AIR CONDITIONER

Summary:

ONLY REPLACEMENT OF EVAPORATOR CORE OR PIPES FOR REAR HVAC. (TO INCLUDE 2005 CHEVROLET TRAILBLAZER) \*SC

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 3019A

Date of Bulletin: JAN 01, 2004

NHTSA Item Number: 10010238

Component: OTHER

Summary:

DIAGNOSTIC TROUBLE CODE P0171 . \*SC SERVICE ENGINE SOON LIGHT DUE TO DIAGNOSTIC TROUBLE CODE P0171. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 3095

Date of Bulletin: JAN 01, 2004

**For TrailVoy.com Members Only**

**For TrailVoy.com Members Only**

NHTSA Item Number: 10010244

Component: VISIBILITY:GLASS, SIDE/REAR

Summary:

OPERATION OF REAR GLASS RELEASE KEY CYLINDER. TO INCLUDE 2005 TRAILBLAZER AND BUICK RAINIER. \*SC

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 3172

Date of Bulletin: JAN 01, 2004

NHTSA Item Number: 10010252

Component: ELECTRICAL SYSTEM

Summary:

MULTIPLE ELECTRICAL CONCERNS AND DIAGNOSTIC TROUBLE CODE U1064. VARIOUS MODELS INCLUDING 2005 BUICK RAINIER AND 2005 CHEVROLET TRAILBLAZER. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 3178

Date of Bulletin: JAN 01, 2004

NHTSA Item Number: 10010261

Component: SEAT BELTS:FRONT

Summary:

DRIVER AND/OR PASSENGER FRONT SEAT BELTS LOCK UP IN RETRACTED POSITION. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 3179

Date of Bulletin: JAN 01, 2004

NHTSA Item Number: 10010266

Component: EQUIPMENT:ELECTRICAL:AIR CONDITIONER

Summary:

AUTOMATIC DUAL ZONE HVAC BATTERY DRAW SUPPLEMENT TO 02-01-39-007A. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 040730002

Date of Bulletin: JAN 01, 2004

NHTSA Item Number: 10011130

Component: POWER TRAIN:AUTOMATIC TRANSMISSION

Summary:

RATTLE TYPE NOISE COMING FROM UNDER THE VEHICLE. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 030604018A

Date of Bulletin: DEC 01, 2003

NHTSA Item Number: 10005152



**For TrailVoy.com Members Only**

Component: ENGINE AND ENGINE COOLING:ENGINE

Summary:

COLD IDLE FLUCTUATION AT ALTITUDE, HESITATION ON ACCELERATION OR 1-2 UPSHIFT DELAY. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 030863003

Date of Bulletin: DEC 01, 2003

NHTSA Item Number: 10005188

Component: STRUCTURE:BODY

Summary:

RATTLE FROM FRONT OF VEHICLE. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 11202003

Date of Bulletin: NOV 20, 2003

NHTSA Item Number: 10013261

Component: POWER TRAIN:AUTOMATIC TRANSMISSION

Summary:

RATTLE NOISE UNDERNEATH THE VEHICLE OR AN AUTOMATIC TRANSMISSION FLUID LEAK. \*EH

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 00817A

Date of Bulletin: NOV 18, 2003

NHTSA Item Number: 10004124

Component: ENGINE AND ENGINE COOLING:ENGINE

Summary:

4.2L LL8 ENGINE STALL WHILE RUNNING EVAP DIAGNOSTICS. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 01354

Date of Bulletin: NOV 18, 2003

NHTSA Item Number: 10004136

Component: ELECTRICAL SYSTEM:BATTERY

Summary:

INTERMITTENT DEAD BATTERY. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 00651B

Date of Bulletin: NOV 18, 2003

NHTSA Item Number: 10004201

Component: EXTERIOR LIGHTING:BRAKE LIGHTS

**For TrailVoy.com Members Only**

**For TrailVoy.com Members Only**

Summary:

REAR BRAKE LIGHT BULB OUT. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 01410

Date of Bulletin: NOV 18, 2003

NHTSA Item Number: 10004214

Component: POWER TRAIN

Summary:

POOR PERFORMANCE FROM A STOP IN 2WD, AUTO OR 4WD HI. 2003, 2003 CADILLAC EXT ALSO INCLUDED.  
\*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 00817C

Date of Bulletin: NOV 18, 2003

NHTSA Item Number: 10004241

Component: ENGINE AND ENGINE COOLING:ENGINE

Summary:

COLD IDLE STALL THAT OCCURS DURING OR IMMEDIATELY AFTER EVAP DIAGNOSTICS ARE RUN. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 030730056

Date of Bulletin: NOV 01, 2003

NHTSA Item Number: 10005566

Component: POWER TRAIN:AUTOMATIC TRANSMISSION

Summary:

4L60-E AUTOMATIC TRANSMISSION OIL PUMP FIRST AND SECOND DESIGN IDENTIFICATION. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 100703

Date of Bulletin: OCT 07, 2003

NHTSA Item Number: 10004980

Component: ENGINE AND ENGINE COOLING:ENGINE

Summary:

INTERMITTENT HESITATION, STUMBLE OR IDLE STALL WITHIN MINUTES OF STARTING AFTER THE VEHICLE HAS BEEN SITTING FOR SEVERAL HOURS. GM VOICEMAIL LOG. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 010850011A

Date of Bulletin: OCT 01, 2003

NHTSA Item Number: 10004736

Component: SEATS:FRONT ASSEMBLY:POWER ADJUST

**For TrailVoy.com Members Only**

Summary:

MEMORY POWER SEAT INOPERATIVE. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 030604057

Date of Bulletin: OCT 01, 2003

NHTSA Item Number: 10004771

Component: ENGINE AND ENGINE COOLING:ENGINE

Summary:

INTERMITTENT HESITATION, STUMBLE OR IDLE STALL AFTER SOAK, HARSH 1-2 SHIFT, SLIPPING 1-2 SHIFT FOLLOWED BY A HARSH ENGAGEMENT. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 510

Date of Bulletin: OCT 01, 2003

NHTSA Item Number: 10016248

Component: ELECTRICAL SYSTEM:BATTERY

Summary:

INTERMITTENT DEAD BATTERY. \*SC

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 092203

Date of Bulletin: SEP 22, 2003

NHTSA Item Number: 10005045

Component: EXTERIOR LIGHTING:TAIL LIGHTS:SWITCH

Summary:

TAIL LAMP CIRCUIT BOARD PART NUMBER INFORMATION. GM VOICEMAIL LOG. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 030842010

Date of Bulletin: SEP 01, 2003

NHTSA Item Number: 10004328

Component: EXTERIOR LIGHTING:HEADLIGHTS

Summary:

DAYTIME RUNNING LAMP FEATURE CANNOT BE DISABLED AFTER BODY CONTROL MODULE (BCM)REPLACEMENT. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 030864032

Date of Bulletin: SEP 01, 2003

NHTSA Item Number: 10004342

Component: VISIBILITY:REARVIEW MIRRORS/DEVICES:EXTERIOR

## For TrailVoy.com Members Only

Summary:

AVAILABILITY OF REPLACEMENT PARTS FOR OUTSIDE REARVIEW MIRROR. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 030864033

Date of Bulletin: SEP 01, 2003

NHTSA Item Number: 10004343

Component: VISIBILITY:REARVIEW MIRRORS/DEVICES:EXTERIOR

Summary:

AVAILABILITY OF REPLACEMENT MIRROR ACTUATOR. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 081103

Date of Bulletin: AUG 11, 2003

NHTSA Item Number: 10003862

Component: CHILD SEAT

Summary:

THIS VME STATES THAT GM HAS DECIDED THAT CERTAIN VEHICLES DO NOT COMPLY WITH FEDERAL MOTOR VEHICLE SAFETY STANDARD 225 IN BOTH US AND CANADA BECAUSE THE OWNERS MANUAL DOES NOT INCLUDE THE LOCATION SYMBOLS FOR THE LOWER UNIVERSAL ANCHORAGE SYSTEM AND EXPLANATION OF THE MEANING OF THE SYMBOLS. RECALL 03039 FOR CHILD SEAT ANCHORAGE SYSTEM. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 030866008

Date of Bulletin: AUG 01, 2003

NHTSA Item Number: 10012578

Component: STRUCTURE:BODY

Summary:

PERIMETER SEAL/GASKET PULLS AWAY FROM LICENSE PLATE HOUSING AND/OR EXCESSIVE ADHESIVE AROUND GASKET. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 030844002

Date of Bulletin: JUL 01, 2003

NHTSA Item Number: 10000946

Component: EQUIPMENT:ELECTRICAL

Summary:

RADIO AND / OR HVAC SYSTEMS CHANGE WHILE DRIVING. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 030604034

Date of Bulletin: JUL 01, 2003

NHTSA Item Number: 10002943

Component: ENGINE AND ENGINE COOLING:ENGINE

For TrailVoy.com Members Only

**For TrailVoy.com Members Only**

Summary:

SERVICE ENGINE SOON LIGHT ON, DIAGNOSTIC TROUBLE CODE P0135 SET. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 062503

Date of Bulletin: JUN 25, 2003

NHTSA Item Number: 10003719

Component: VISIBILITY:WINDSHIELD WIPER/WASHER:LINKAGES

Summary:

WINDSHIELD WASHER NOZZLES BEING CLOGGED IR AIMED IMPROPERLY. VME MESSAGE. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 062503

Date of Bulletin: JUN 25, 2003

NHTSA Item Number: 10003721

Component: STRUCTURE

Summary:

REAR LICENSE PLATE POCKET SEAL BEING ROLLED OVER DUE TO IMPROPER INSTALLATION. THIS A VME MESSAGE. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 061903

Date of Bulletin: JUN 19, 2003

NHTSA Item Number: 10003710

Component: POWER TRAIN

Summary:

UNUSUAL VIBRATION FELT AT IDLE OR AT VERY LOW RPM DURING PARKING LOT MANEUVERS. ALSO RESIDENCE NOISE ACCOMPANYING THE VIBRATION. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 061803

Date of Bulletin: JUN 18, 2003

NHTSA Item Number: 10003706

Component: VISIBILITY:POWER WINDOW DEVICES AND CONTROLS

Summary:

POWER WINDOW MOTORS OCCASIONALLY OR INTERMITTENTLY INOPERATIVE. DIAGNOSIS/TROUBLESHOOTING. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 060603

Date of Bulletin: JUN 06, 2003

NHTSA Item Number: 10003695

Component: ENGINE AND ENGINE COOLING:ENGINE

**For TrailVoy.com Members Only**

**For TrailVoy.com Members Only**

Summary:

CRACKING OF AN ENGINE CYLINDER BORE LINER RESULTING IN ENGINE NOISE, POOR PERFORMANCE AND/OR STALLS WITH NO ENGINE RESTART. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 030139007                      Date of Bulletin: JUN 01, 2003  
NHTSA Item Number: 10002131  
Component: EQUIPMENT:ELECTRICAL:AIR CONDITIONER

Summary:

AIR CONDITIONING (A/C) INOPERATIVE / INTERMITTENT, AIR CONDITIONER BLOWS WARM AIR. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 010846002C                      Date of Bulletin: JUN 01, 2003  
NHTSA Item Number: 10002836  
Component: EQUIPMENT

Summary:

PROGRAMMING OF REPLACEMENT ONSTAR VEHICLE COMMUNICATION AND INTERFACE MODULES (VCIM). \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 030842006                      Date of Bulletin: JUN 01, 2003  
NHTSA Item Number: 10002867  
Component: EXTERIOR LIGHTING:TAIL LIGHTS:SWITCH

Summary:

TAIL LAMP CIRCUIT BOARD NOW AVAILABLE FOR SERVICE USE. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 030866006                      Date of Bulletin: JUN 01, 2003  
NHTSA Item Number: 10002877  
Component: STRUCTURE:BODY:HATCHBACK/LIFTGATE

Summary:

LIFT GATE GLASS HARD TO CLOSE. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 030867004                      Date of Bulletin: JUN 01, 2003  
NHTSA Item Number: 10002878  
Component: VISIBILITY:SUN ROOF ASSEMBLY

**For TrailVoy.com Members Only**

## For TrailVoy.com Members Only

Summary:

PARTS AVAILABILITY FOR SUNROOF REPAIRS. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 03019

Date of Bulletin: JUN 01, 2003

NHTSA Item Number: 10003392

Component: ENGINE AND ENGINE COOLING:ENGINE

Summary:

SPECIAL POLICY ADJUSTMENT 03019 - 4.2L BORE LINER CRACKING RESULTING IN ENGINE NOISE, POOR PERFORMANCE, AND/OR STALLS WITH NO ENGINE RESTART. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 052303

Date of Bulletin: MAY 23, 2003

NHTSA Item Number: 10003671

Component: EQUIPMENT:ELECTRICAL:AIR CONDITIONER

Summary:

AIR CONDITIONER LOW PRESSURE CYCLING SWITCH INTERMITTENTLY INOPERATIVE OR STUCK OPEN/ INTERMITTENT AIR CONDITIONER OPERATION AND/OR LOSS OF COLD AIR. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 052203

Date of Bulletin: MAY 22, 2003

NHTSA Item Number: 10003659

Component: POWER TRAIN

Summary:

PRODUCT FIELD ACTION 03012. VEHICLES ARE EQUIPPED WITH A MECHANICAL OVERRIDE THAT COULD ALLOW THE IGNITION KEY TO BE REMOVED WITH THE SHIFT LEVER IN A POSITION OTHER THAN PARK. IN ADDITION, THESE VEHICLES HAVE AN OVERRIDE THAT CAN ALLOW THE TRANSMISSION TO BE SHIFTED OUT OF PARK WITH THE IGNITION IN THE OFF POSITION. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 052203

Date of Bulletin: MAY 22, 2003

NHTSA Item Number: 10003660

Component: ELECTRICAL SYSTEM

Summary:

INTERMITTENT CONDITION AT VEHICLE START UP IN WHICH THE INSTRUMENT PANEL CLUSTER MAY NOT POWER UP RESULTING IN MOST OF THE DISPLAYS, TELLTALE LIGHTS AND FUNCTIONS BEING INOPERATIVE. DEALERS ARE TO REPROGRAM THE INSTRUMENT CLUSTER SOFTWARE. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 03013

Date of Bulletin: MAY 01, 2003

For TrailVoy.com Members Only

**For TrailVoy.com Members Only**

NHTSA Item Number: 10001782

Component: ELECTRICAL SYSTEM

Summary:

INSTRUMENT PANEL CLUSTER GAUGES INOPERATIVE. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 020139006A

Date of Bulletin: MAY 01, 2003

NHTSA Item Number: 10002366

Component: EQUIPMENT:ELECTRICAL:AIR CONDITIONER

Summary:

DIAGNOSING POOR AIR CONDITIONER PERFORMANCE - AIR CONDITIONER STOPS BLOWING COLD, AIR CONDITIONER CYCLES ON AND OFF. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 030842004

Date of Bulletin: MAY 01, 2003

NHTSA Item Number: 10002391

Component: EXTERIOR LIGHTING:HEADLIGHTS:HIGH/LOW BEAM DIMMER SWITCH

Summary:

HEADLAMP LOW BEAM BULB SOCKET NOW AVAILABLE FOR SERVICE USE. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 031303

Date of Bulletin: MAR 13, 2003

NHTSA Item Number: 10001910

Component: ENGINE AND ENGINE COOLING:ENGINE

Summary:

IDLE FLUCTUATION AND/OR HESITATION ON ACCELERATION. \*TT \*JB

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 031303

Date of Bulletin: MAR 13, 2003

NHTSA Item Number: 10001911

Component: POWER TRAIN

Summary:

1-2 UPSHIFT DELAY CONDITION AT THROTTLE OPENINGS. \*TT \*JB

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 031303

Date of Bulletin: MAR 13, 2003

NHTSA Item Number: 10001913

**For TrailVoy.com Members Only**



## For TrailVoy.com Members Only

Component: EXTERIOR LIGHTING:HEADLIGHTS

Summary:

UNABLE TO DISABLE THE DAYTIME RUNNING LAMP FEATURE WHEN FOLLOWING THE PROCEDURE IN THE OWNER'S MANUAL. \*TT \*JB

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 031003

Date of Bulletin: MAR 10, 2003

NHTSA Item Number: 10001903

Component: STRUCTURE:BODY:HATCHBACK/LIFTGATE

Summary:

THE LIFT GATE, OR LIFT GATE GLASS, BINDS WHEN OPENING OR DOES NOT OPEN COMPLETELY BECAUSE OF CENTER HIGH MOUNTED STOP LAMP OR CHIMSEL APPLIQUE HITS THE ROOF OF THE VEHICLE. \*TT \*JB

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 030604018

Date of Bulletin: MAR 01, 2003

NHTSA Item Number: 10001267

Component: ENGINE AND ENGINE COOLING:ENGINE

Summary:

COLD IDLE FLUCTUATION AT ALTITUDE, HESITATION ON ACCELERATION OR 1-2 UPSHIFT DELAY. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 020235006A

Date of Bulletin: MAR 01, 2003

NHTSA Item Number: 10001270

Component: STEERING

Summary:

SQUEAK, RUB / SCRUB TYPE NOISE IN STEERING COLUMN. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 020421008A

Date of Bulletin: FEB 01, 2003

NHTSA Item Number: 10001101

Component: POWER TRAIN:AUTOMATIC TRANSMISSION

Summary:

SHUDDER, ROCKING MOTION, BINDING, FEELS LIKE VEHICLE IS TUCK IN 4WD WHEN TURNING AT LOW SPEEDS. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 030417002

Date of Bulletin: FEB 01, 2003

NHTSA Item Number: 10001111

**For TrailVoy.com Members Only**

Component: POWER TRAIN:AXLE ASSEMBLY

Summary:

WHINE NOISE FROM REAR AXLE. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 020421002A

Date of Bulletin: FEB 01, 2003

NHTSA Item Number: 10001144

Component: POWER TRAIN:TRANSFER CASE (4-WHEEL DRIVE)

Summary:

SERVICE 4WD INDICATOR ILLUMINATED, DIAGNOSTIC TROUBLE CODE (DTC) B2725 SET, TRANSFER CASE SELECTOR SWITCH IS IN ONE POSITION - INDICATOR LAMP INDICATES ANOTHER RANGE IS SELECTED. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 012903

Date of Bulletin: JAN 29, 2003

NHTSA Item Number: 10005113

Component: STRUCTURE:FRAME AND MEMBERS

Summary:

INFORMATION ON REPLACING A FULL FRAME ASSEMBLY ON A COLLISION REPAIR. GM VOICEMAIL EXPRESS. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 012103

Date of Bulletin: JAN 21, 2003

NHTSA Item Number: 10005095

Component: ENGINE AND ENGINE COOLING:COOLING SYSTEM

Summary:

ENGINE OVERHEAT CONDITION WITH LITTLE OR NO HEATER OUTPUT. OASIS \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 011703

Date of Bulletin: JAN 17, 2003

NHTSA Item Number: 10005108

Component: SERVICE BRAKES, HYDRAULIC

Summary:

FRONT BRAKE NOISE OR SQUEALING AFTER THE VEHICLES HAS SAT OVERNIGHT. GM VOICEMAIL EXPRESS. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 030604011

Date of Bulletin: JAN 01, 2003

NHTSA Item Number: 10000942

**For TrailVoy.com Members Only**

**For TrailVoy.com Members Only**

Component: EQUIPMENT:ELECTRICAL

Summary:

PROGRAMMING / RE-PROGRAMMING, SETUP, CONFIGURATION OF MODULES. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 121302

Date of Bulletin: DEC 13, 2002

NHTSA Item Number: 10002751

Component: EQUIPMENT:ELECTRICAL

Summary:

ERROR MESSAGES WHEN PROGRAMMING A NEW MODULE. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 120902

Date of Bulletin: DEC 09, 2002

NHTSA Item Number: 10002739

Component: STRUCTURE:BODY

Summary:

BUZZ OR RATTLE NOISE COMING FROM THE FRONT END OF LIGHT ACCELREATION AT 25 TO 45 MILES PER HOUR OR OVER BUMPS. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 020843006

Date of Bulletin: DEC 01, 2002

NHTSA Item Number: 10000721

Component: VISIBILITY:REAR WINDOW WIPER/WASHER

Summary:

REVISED WIPER INOPERATIVE - REAR DIAGNOSTIC. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 020419001

Date of Bulletin: DEC 01, 2002

NHTSA Item Number: 10000723

Component: POWER TRAIN:DRIVELINE:DIFFERENTIAL UNIT

Summary:

REVISED DIFFERENTIAL CARRIER ASSEMBLY REPLACEMENT. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 020138006

Date of Bulletin: DEC 01, 2002

NHTSA Item Number: 10000737

Component: EQUIPMENT:ELECTRICAL

**For TrailVoy.com Members Only**

**For TrailVoy.com Members Only**

Summary:

REVISED COMPRESSOR OIL BALANCING PROCEDURE. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 020844016A

Date of Bulletin: DEC 01, 2002

NHTSA Item Number: 10000747

Component: STRUCTURE:BODY

Summary:

WHINE, BUZZ, GENERATOR WHINE, WHINE TYPE NOISE HEARD ON ACCELERATION. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 020864024

Date of Bulletin: DEC 01, 2002

NHTSA Item Number: 10000750

Component: STRUCTURE:BODY

Summary:

DISCOLORATION / FADING OF DOOR GLASS MOLDING. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 020849004A

Date of Bulletin: NOV 01, 2002

NHTSA Item Number: 10000461

Component: ELECTRICAL SYSTEM:WIRING:INTERIOR/UNDER DASH

Summary:

INSTRUMENT PANEL CLUSTER (IPC) GAUGES READ ZERO AT TIMES, GAUGES INOPERATIVE AT TIMES. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 020862004

Date of Bulletin: NOV 01, 2002

NHTSA Item Number: 10000463

Component: STRUCTURE:BODY

Summary:

FRONT FASCIA WAVY. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 11012002

Date of Bulletin: NOV 01, 2002

NHTSA Item Number: 10009580

Component: EXTERIOR LIGHTING:TAIL LIGHTS

Summary:

SERVICING THE REAR TAIL LAMP BULB OR SOCKET ASSEMBLY. \*TT

---

**For TrailVoy.com Members Only**

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 10082002                      Date of Bulletin: OCT 08, 2002  
NHTSA Item Number: 10013130  
Component: OTHER

Summary:  
IDL EMERGING ISSUES BROADCAST COVERING TOPICS SUCH AS THE ONSTAR, CALIFORNIA EMISSIONS, AN OVERVIEW OF THE EVAP OPERATION, WIRING ISSUES FOR THE SEATS, AND SHUTTER DURING PARKING LOT MANEUVERS. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 020864021                      Date of Bulletin: OCT 01, 2002  
NHTSA Item Number: 10000160  
Component: VISIBILITY:REARVIEW MIRRORS/DEVICES:EXTERIOR

Summary:  
OUTSIDE REARVIEW MIRRORS DO NOT RETURN TO THEIR ORIGINAL POSITION AFTER USING CURB VIEW ASSIST FEATURE. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 020849009                      Date of Bulletin: OCT 01, 2002  
NHTSA Item Number: 10000164  
Component: STRUCTURE

Summary:  
INTERFERENCE WITH CENTER CONSOLE REAR AUXILIARY POWER OUTLET COVER AND REAR SEAT CUSHION. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 020601032                      Date of Bulletin: OCT 01, 2002  
NHTSA Item Number: 10000168  
Component: ENGINE AND ENGINE COOLING:EXHAUST SYSTEM

Summary:  
EXHAUST NOISE / LEAK. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 020601033                      Date of Bulletin: OCT 01, 2002  
NHTSA Item Number: 10000169  
Component: ENGINE AND ENGINE COOLING:ENGINE

Summary:  
OIL LEAK AT OIL PRESSURE SWITCH. \*TT

---

**For TrailVoy.com Members Only**

**For TrailVoy.com Members Only**

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 020421006A                      Date of Bulletin: OCT 01, 2002  
NHTSA Item Number: 10000173  
Component: POWER TRAIN:TRANSFER CASE (4-WHEEL DRIVE)  
Summary:  
    INOPERATIVE 4WD/AWD LAMPS, INOPERATIVE 4WD/AWD SYSTEM. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 020421008                      Date of Bulletin: OCT 01, 2002  
NHTSA Item Number: 10000174  
Component: POWER TRAIN  
Summary:  
    SHUDDER, ROCKING MOTION, BINDING, FEELS LIKE VEHICLE IS STUCK IN 4WD (CROW HOP) WHEN TURNING AT LOW SPEEDS. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 020535006                      Date of Bulletin: OCT 01, 2002  
NHTSA Item Number: 10000175  
Component: STEERING:COLUMN  
Summary:  
    SQUEAK NOISE IN STEERING COLUMN. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 020139006                      Date of Bulletin: OCT 01, 2002  
NHTSA Item Number: 10000178  
Component: EQUIPMENT:ELECTRICAL:AIR CONDITIONER  
Summary:  
    DIAGNOSING POOR AIR CONDITIONER PERFORMANCE - AIR CONDITIONER STOPS BLOWING COLD, AIR CONDITIONER CYCLES ON AND OFF. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 09242002                      Date of Bulletin: SEP 24, 2002  
NHTSA Item Number: 10008626  
Component: VISIBILITY:REARVIEW MIRRORS/DEVICES:EXTERIOR  
Summary:  
    OUTSIDE MIRRORS DO NOT RETURN TO THE ORIGINAL POSITION AFTER USING THE REVERSE TILT CURB ASSIST FEATURE. \*TT

---

**For TrailVoy.com Members Only**

**For TrailVoy.com Members Only**

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 09052002                      Date of Bulletin: SEP 05, 2002  
NHTSA Item Number: 10009457  
Component: STRUCTURE:BODY  
Summary:  
    TAPPING NOISE AND INSTALLATION CONCERNS WITH THE MOLDED HOOD PROTECTOR. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 020139005                      Date of Bulletin: SEP 01, 2002  
NHTSA Item Number: 10000058  
Component: EQUIPMENT  
Summary:  
    HVAC SYSTEM INOPERATIVE FOR A DRIVE CYCLE, POOR HVAC SYSTEM PERFORMANCE IN HIGH AMBIENT TEMPERATURES. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 020309002A                      Date of Bulletin: SEP 01, 2002  
NHTSA Item Number: 10000060  
Component: SUSPENSION  
Summary:  
    INTERMITTENT BOOM, RUMBLING NOISE AND / OR DISTURBANCE HEARD IN PASSENGER COMPARTMENT WHILE DRIVING AT HIGHWAY SPEEDS. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 020940003                      Date of Bulletin: SEP 01, 2002  
NHTSA Item Number: 10000079  
Component: SEAT BELTS  
Summary:  
    PASSENGER SEAT SHOULDER BELT TOO TIGHT OR CINCHES UP. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 020862001                      Date of Bulletin: AUG 01, 2002  
NHTSA Item Number: 634312  
Component: STRUCTURE:BODY  
Summary:  
    SOME CUSTOMERS MAY COMMENT THAT THE FRONT FASCIA ON THE VEHICLE APPEARS TO BE LOOSE.  
\*TT

---

**For TrailVoy.com Members Only**

**For TrailVoy.com Members Only**

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 020864017                      Date of Bulletin: AUG 01, 2002  
NHTSA Item Number: 634314  
Component: ELECTRICAL SYSTEM  
Summary:  
SOME CUSTOMES MAY COMMENT THAT THE VEHICLE WILL NOT START AND / OR THE DOOR ELECTRICAL FUNCTIONS MAY BE INOPERATIVE. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 020309002                      Date of Bulletin: AUG 01, 2002  
NHTSA Item Number: 634866  
Component: SUSPENSION  
Summary:  
SOME CUSTOMERS MAY COMMENT ON AN INTERMITTENT BOOMING, RUMBLING NOISE AND / OR DISTURBANCE HEARD IN THE PASSENGER COMPARTMENT WHILE DRIVING AT HIGHWAY SPEEDS. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 190702                      Date of Bulletin: JUL 19, 2002  
NHTSA Item Number: 637300  
Component: OTHER  
Summary:  
CUSTOMERS MAY COMMENT THAT THE SERVICE FOUR-WHEEL DRIVE / ALL-WHELL DRIVE INDICATOR ILLUMINATED OR THE FOUR-WHEEL DRIVE / ALL-WHEEL DRIVE IS INOPERATIVE. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 020139003A                      Date of Bulletin: JUL 01, 2002  
NHTSA Item Number: 634886  
Component: VISIBILITY:DEFROSTER/DEFOGGER SYSTEM  
Summary:  
CONCERNS WITH EXT AND XL MODELS EXHIBITING INOPERATIVE REAR HVAC CONTROLS AND / OR DIAGNOSTIC TROUBLE CODE B0150. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 020421006                      Date of Bulletin: JUL 01, 2002  
NHTSA Item Number: 634893  
Component: POWER TRAIN:AUTOMATIC TRANSMISSION:LEVER AND LINKAGE:COLUMN SHIFT  
Summary:  
SOME CUSTOMERS MAY COMMENT THAT THE 4WD/AWD INDICATOR LIGHTS ON THE SELECTOR SWITCH DO NOT WORK OR THE 4WD/AWD SYSTEM MAY BE INOPERATIVE. \*TT

**For TrailVoy.com Members Only**



**For TrailVoy.com Members Only**

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 0208111004

Date of Bulletin: JUN 01, 2002

NHTSA Item Number: 634512

Component: EQUIPMENT:OTHER:LABELS

Summary:

SOME EXT OWNERS MAY COMMENT THAT THE EMBLEM ON THE REAR SIDE DOORS READS LTZ. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 020849004

Date of Bulletin: JUN 01, 2002

NHTSA Item Number: 634663

Component: OTHER

Summary:

SOME CUSTOMERS MAY COMMENT THAT AT TIMES ALL THE INSTRUMENT PANEL CLUSTER GAUGES ARE INOPERATIVE OR READ ZERO AT TIMES. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 020861002

Date of Bulletin: JUN 01, 2002

NHTSA Item Number: 634667

Component: STRUCTURE:BODY

Summary:

SOME CUSTOMERS MAY COMMENT THAT THE ASSIST STEP SKID PAD IS WARPED. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 080902

Date of Bulletin: MAY 09, 2002

NHTSA Item Number: 636634

Component: ELECTRICAL SYSTEM:WIRING

Summary:

INFORMATION ON DIAGNOSING ELECTRICAL WIRING CONNECTOR PROBLEMS ON 2000 THROUGH 2001 U-VANS AS WELL AS OTHER MODELS. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 02016

Date of Bulletin: MAY 08, 2002

NHTSA Item Number: 636624

Component: FUEL SYSTEM, GASOLINE:DELIVERY:HOSES, LINES/PIPING, AND FITTINGS

Summary:

PRODUCT SAFETY RECALL 02016 REGARDING A CONDITION WHERE A FUEL FILTER FITTING MAY BECOME DISCONNECTED. \*TT

---

**For TrailVoy.com Members Only**

**For TrailVoy.com Members Only**

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 020867005                      Date of Bulletin: MAY 01, 2002  
NHTSA Item Number: 634557  
Component: EQUIPMENT:MECHANICAL:CARRIER/RACK  
Summary:  
SUBJECT REGARDING PROPER POSITION AND INSTALLATION OF ROOF RACK CROSS RAILS TO REDUCE WIND NOISE. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 020846008                      Date of Bulletin: MAY 01, 2002  
NHTSA Item Number: 634571  
Component: OTHER  
Summary:  
INFORMATION REGARDING THE ON-STAR MODULE COVER RETAINING TAB BREAKING. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 020867004                      Date of Bulletin: MAY 01, 2002  
NHTSA Item Number: 634583  
Component: STRUCTURE  
Summary:  
SOME CUSTOMERS MAY COMMENT THAT THE HEADLINER SAGS AT THE REAR OF THE SUNROOF OPENING. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 020846005                      Date of Bulletin: MAY 01, 2002  
NHTSA Item Number: 634678  
Component: ELECTRICAL SYSTEM:IGNITION:MODULE  
Summary:  
SUBJECT REGARDING THE ADDITION OF DIAGNOSTIC TROUBLE CODE U1500 FOR GENERATION 4 ONSTAR. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 020601020                      Date of Bulletin: MAY 01, 2002  
NHTSA Item Number: 634721  
Component: OTHER  
Summary:  
SUBJECT REGARDING CHANGE TO FLYWHEEL TO CRANKSHAFT ATTACHING BOLTS. \*TT

---

**For TrailVoy.com Members Only**

**For TrailVoy.com Members Only**

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 020139003                      Date of Bulletin: MAY 01, 2002  
NHTSA Item Number: 634889  
Component: VISIBILITY:DEFROSTER/DEFOGGER SYSTEM  
Summary:  
CONCERNS WITH EXT AND XL MODELS EXHIBITING INOPERATIVE REAR HVAC CONTROLS AND / OR DIAGNOSTIC TROUBLE CODE B0150. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 043002                      Date of Bulletin: APR 30, 2002  
NHTSA Item Number: 636586  
Component: EQUIPMENT:MECHANICAL:CARRIER/RACK  
Summary:  
INFORMATION ON INSTALLING ROOF RACK CROSSBOWS REVERSED TO REDUCE WIND NOISE. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 042602                      Date of Bulletin: APR 26, 2002  
NHTSA Item Number: 636577  
Component: STRUCTURE:BODY  
Summary:  
SUBJECT REGARDING VEHICLES INCORRECTLY BUILT WITH LTZ BADGES ON THE B-PILLARS. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 041502                      Date of Bulletin: APR 15, 2002  
NHTSA Item Number: 636540  
Component: ENGINE AND ENGINE COOLING:COOLING SYSTEM:RADIATOR ASSEMBLY  
Summary:  
INFORMATION PERTAINING TO THE UNDERHOOD UPPER RADIATOR SUPPORT BAFFLE OR BEAUTY COVER.  
\*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 020866004                      Date of Bulletin: APR 01, 2002  
NHTSA Item Number: 634552  
Component: STRUCTURE:BODY  
Summary:  
SOME CUSTOMERS MAY COMMENT THAT THE PAINT ON THE LIFTGATE AROUND THE EDGES OF THE LICENSE PLATE HOUSING OR POCKET APPEARS TO BE RUBBING THROUGH OR WEARING OFF. \*TT

---

**For TrailVoy.com Members Only**

**For TrailVoy.com Members Only**

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 020864008                      Date of Bulletin: APR 01, 2002  
NHTSA Item Number: 634554  
Component: VISIBILITY:REARVIEW MIRRORS/DEVICES:EXTERIOR

Summary:  
SOME CUSTOMERS MAY COMMENT THAT THE OUTSIDE REARVIEW MEMORY MIRRORS MAY WANDER OR MAY NOT GO BACK TO A PREVIOUSLY SET POSITION. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 020601012                      Date of Bulletin: APR 01, 2002  
NHTSA Item Number: 634690  
Component: ENGINE AND ENGINE COOLING:ENGINE:GASOLINE

Summary:  
INFORMATION PERTAINING TO REVISED HARMONIC BALANCER. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 0090001                      Date of Bulletin: MAR 01, 2002  
NHTSA Item Number: 632320  
Component: ENGINE AND ENGINE COOLING:ENGINE:GASOLINE

Summary:  
SUBJECT REGARDING GM OIL LIFE SYSTEM. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 070202                      Date of Bulletin: FEB 07, 2002  
NHTSA Item Number: 629762  
Component: ENGINE AND ENGINE COOLING:ENGINE:GASOLINE

Summary:  
SUBJECT REGARDING ENGINE DAMAGE OF REPLACEMENT ENGINES ATTRIBUTED TO DEBRIS FROM THE INTAKE MANIFOLD BEING TRANSFERRED FROM THE ORIGINAL ENGINE. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 020421002                      Date of Bulletin: FEB 01, 2002  
NHTSA Item Number: 629356  
Component: OTHER

Summary:  
SOME OWNERS MAY COMMENT ON THE SERVICE 4WD INDICATOR ILLUMINATING, IN ADDITION TO DIAGNOSTIC TROUBLE CODE B2725. \*TT

---

**For TrailVoy.com Members Only**

**For TrailVoy.com Members Only**

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 290102                      Date of Bulletin: JAN 29, 2002  
NHTSA Item Number: 629732

Component: POWER TRAIN:AUTOMATIC TRANSMISSION:LEVER AND LINKAGE:COLUMN SHIFT

Summary:  
INFORMATION ON PROPER PROGRAMMING FOR THE TRANSFER CASE CONTROL MODULE. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 020603001                      Date of Bulletin: JAN 01, 2002  
NHTSA Item Number: 628833

Component: ELECTRICAL SYSTEM

Summary:  
CONCERNS WITH NO START, TURN/HAZARD, INTERIOR LAMPS, DRIVER INFORMATION CENTER (DIC), RADIO, THEFT ALARM, WIPERS, CRUISE, SHIFT INTERLOCK, HORN AND/OR KEY IN SIGNAL INOPERATIVE. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 010138014                      Date of Bulletin: JAN 01, 2002  
NHTSA Item Number: 628850

Component: VISIBILITY:DEFROSTER/DEFOGGER SYSTEM

Summary:  
SOME CUSTOMERS MAY COMMENT THAT THE HEATER DOES NOT WARM THE DRIVER'S FEET. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 41                      Date of Bulletin: JAN 01, 2002  
NHTSA Item Number: 637390

Component: EQUIPMENT:ELECTRICAL:RADIO/TAPE DECK/CD ETC.

Summary:  
SUBJECT REGARDING RADIO SPEAKER NOISE WITH BRAKE APPLIED. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 131201                      Date of Bulletin: DEC 13, 2001  
NHTSA Item Number: 628807

Component: ELECTRICAL SYSTEM:WIRING:INTERIOR/UNDER DASH

Summary:  
SUBJECT REGARDING BULLETIN 010604052 ON BOARD DIAGNOSTIC (OBD) SYSTEM IMPROVEMENTS UPGRADE. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002

**For TrailVoy.com Members Only**

**For TrailVoy.com Members Only**

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 131201

Date of Bulletin: DEC 13, 2001

NHTSA Item Number: 629619

Component: POWER TRAIN

Summary:

SUBJECT REGARDING SERVICE ENGINE SOON LIGHT ON, DELAYED TRANSMISSION DOWNSHIFT AND/OR EXCESSIVE FAN NOISE. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 010730043

Date of Bulletin: DEC 01, 2001

NHTSA Item Number: 628815

Component: POWER TRAIN:AUTOMATIC TRANSMISSION

Summary:

SUBJECT REGARDING DIAGNOSTIC TIPS FOR SLIPPING OR MISSING SECOND, THIRD AND/OR FOURTH GEAR. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 010730038

Date of Bulletin: DEC 01, 2001

NHTSA Item Number: 628934

Component: POWER TRAIN:AUTOMATIC TRANSMISSION

Summary:

SOME CUSTOMERS MAY COMMENT THAT THE SERVICE ENGINE SOON LAMP IS ILLUMINATED, NO 3RD AND 4TH GEAR, THE TRANSMISSION DOES NOT SHIFT CORRECTLY, THE TRANSMISSION FEELS LIKE IT SHIFTS TO NEUTRAL OR A LOSS OF DRIVE OCCURS. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 010308005

Date of Bulletin: DEC 01, 2001

NHTSA Item Number: 632359

Component: SUSPENSION

Summary:

THIS BULLETIN IS BEING ISSUED TO CLARIFY THE TORQUE SPECIFICATIONS AND THE PROPER TIGHTENING SEQUENCE FOR THE FASTENERS UTILIZED TO SECURE THE LOWER CONTROL ARM BRACKET TO THE VEHICLE FRAME. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 141101

Date of Bulletin: NOV 14, 2001

NHTSA Item Number: 628130

Component: POWER TRAIN:AXLE ASSEMBLY:AXLE SHAFT:SEAL

Summary:

CUSTOMERS MAY INDICATE A CONCERN OF A FRONT AXLE SEAL HIGH-PITCHED NOISE COMING FROM THE FRONT OF THE VEHICLE AFTER DRIVING ABOUT TEN MILES. \*TT

**For TrailVoy.com Members Only**

**For TrailVoy.com Members Only**

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 010864019                      Date of Bulletin: NOV 01, 2001  
NHTSA Item Number: 627834  
Component: VISIBILITY:REARVIEW MIRRORS/DEVICES:EXTERIOR  
Summary:  
    INFORMATION REGARDING CLICK OR RATCHET TYPE NOISE FROM OUTSIDE REARVIEW MIRRORS. \*YH

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 010730036                      Date of Bulletin: NOV 01, 2001  
NHTSA Item Number: 627912  
Component: POWER TRAIN:MANUAL TRANSMISSION  
Summary:  
    SERVICE ENGINE SOON LAMP ILLUMINATED, INCORRECT TRANSMISSION SHIFTS, POOR PERFORMANCE OF ENGINE, TRANSMISSION SLIPPING. \*YH

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 010604052                      Date of Bulletin: NOV 01, 2001  
NHTSA Item Number: 628817  
Component: ENGINE AND ENGINE COOLING:ENGINE:GASOLINE  
Summary:  
    SOME OWNERS MAY COMMENT ON THE SERVICE ENGINE SOON LAMP BEING ILLIMINATED, A DELAYED TRANSMISSION DOWNSHIFT AND/OR EXCESSIVE FAN NOISE. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 010849016                      Date of Bulletin: NOV 01, 2001  
NHTSA Item Number: 631820  
Component: EQUIPMENT:ELECTRICAL  
Summary:  
    VEHICLES MAY EXPERIENCE AN INOPERATIVE CIGARETTE LIGHTER. \*SLC

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 311001                      Date of Bulletin: OCT 31, 2001  
NHTSA Item Number: 628066  
Component: ENGINE AND ENGINE COOLING:COOLING SYSTEM:FAN  
Summary:  
    BRIEF INFORMATION REGARDING THE AVAILABILITY OF AN ENHANCED CALIBRATION FOR ENGINE COOLING FAN NOISE AND P1484 DIAGNOSTIC TROUBLE CODE. \*TT

---

**For TrailVoy.com Members Only**





**For TrailVoy.com Members Only**

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 161001                      Date of Bulletin: OCT 16, 2001  
NHTSA Item Number: 628000  
Component: POWER TRAIN:AUTOMATIC TRANSMISSION

Summary:  
SOME ALL-WHEEL DRIVE OR FOUR-WHEEL DRIVE VEHICLES MAY EXHIBIT A BUMP OR SURGE THAT CAN OCCUR WHILE THE TRANSMISSION IS STILL IN FIRST GEAR. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 111001                      Date of Bulletin: OCT 11, 2001  
NHTSA Item Number: 627979  
Component: ENGINE AND ENGINE COOLING:ENGINE:GASOLINE

Summary:  
INFORMATION ON RECALIBRATING VEHICLES EXHIBITING A SERVICE ENGINE SOON LAMP ON, A DELAYED DOWNSHIFT OF THE TRANSMISSION AND/OR EXCESSIVE ENGINE FAN NOISE. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 021001                      Date of Bulletin: OCT 02, 2001  
NHTSA Item Number: 627865  
Component: ELECTRICAL SYSTEM:IGNITION:MODULE

Summary:  
INFORMATION REGARDING ENGINE SOON LAMP BEING ILLUMINATED FOR DIAGNOSTIC TROUBLE CODE,P0014, P1683 OR P0116 A DELAYED TRANSMISSION DOWNSHIFT AND/OR EXCESSIVE FAN NOISE. \*YH

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 200901                      Date of Bulletin: SEP 20, 2001  
NHTSA Item Number: 626275  
Component: EQUIPMENT:ELECTRICAL

Summary:  
CONCERNS WITH UNDERSTANDING THE DRIVER INFORMATION PERSONALIZATION LANGUAGE OPTIONS.  
\*SLC

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 010850011                      Date of Bulletin: SEP 01, 2001  
NHTSA Item Number: 627410  
Component: SEATS:FRONT ASSEMBLY:POWER ADJUST

Summary:  
MEMORY POWER SEAT INOPERATIVE. \*YH

---

**For TrailVoy.com Members Only**

**For TrailVoy.com Members Only**

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 300801                      Date of Bulletin: AUG 30, 2001  
NHTSA Item Number: 625359  
Component: ELECTRICAL SYSTEM:IGNITION:MODULE  
Summary:  
    INFORMATION REGARDING UNRESOLVED DTC P0014, FALSE DTC P0116 AND P1683. \*YH

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 300801                      Date of Bulletin: AUG 30, 2001  
NHTSA Item Number: 625364  
Component: POWER TRAIN:MANUAL TRANSMISSION  
Summary:  
    INFORMATION REGARDING DELAYS IN TRANSMISSION DOWNSHIFTING. \*YH

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 300801                      Date of Bulletin: AUG 30, 2001  
NHTSA Item Number: 625366  
Component: ENGINE AND ENGINE COOLING:COOLING SYSTEM:FAN  
Summary:  
    INFORMATION REGARDING FAN NOISE. \*YH

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 290801                      Date of Bulletin: AUG 29, 2001  
NHTSA Item Number: 620850  
Component: ENGINE AND ENGINE COOLING:ENGINE:GASOLINE  
Summary:  
    SUBJECT REGARDING CALIBRATIONS AVAILABLE TO CORRECT UNRESOLVED DIAGNOSTIC TROUBLE CODE P0014, DELAYS IN TRANSMISSION DOWNSHIFTING AND COMPLAINTS OF FAN NOISE. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 080801                      Date of Bulletin: AUG 08, 2001  
NHTSA Item Number: 625369  
Component: ENGINE AND ENGINE COOLING:ENGINE:GASOLINE  
Summary:  
    INFORMATION REGARDING CALIBRATIONS AVAILABLE TO CORRECT DELAYS IN TRANSMISSION DOWNSHIFTING AND COMPLAINTS OF FAN NOISE. \*JG

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002

**For TrailVoy.com Members Only**

**For TrailVoy.com Members Only**

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 010846005

Date of Bulletin: AUG 01, 2001

NHTSA Item Number: 624008

Component: EQUIPMENT:ELECTRICAL

Summary:

UNABLE TO CONNECT TO ONSTAR FOLLOWING A DROPPED CELLULAR CALL DURING AN ONSTAR CONFIGURATION ATTEMPT. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 130701

Date of Bulletin: JUL 13, 2001

NHTSA Item Number: 623808

Component: SERVICE BRAKES, HYDRAULIC:ANTILOCK:ABS WARNING LIGHT

Summary:

CUSTOMERS MAY COMPLAIN OF AN ANTI-LOCK BRAKE SYSTEM (ABS) OR BRAKE INDICATOR LIGHT ILLUMINATING OR A SERVICE BRAKE SYSTEM MESSAGE FROM THE DRIVER INFORMATION CENTER WITH A CODE OF C0238 IN THE ELECTRONIC BRAKE CONTROL MODULE. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 030701

Date of Bulletin: JUL 03, 2001

NHTSA Item Number: 623659

Component: POWER TRAIN:AUTOMATIC TRANSMISSION:LEVER AND LINKAGE:COLUMN SHIFT

Summary:

CUSTOMERS MAY COMPLAIN OF 4-WHEEL DRIVE LIGHT ILLUMINATING.\*JB

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 030701

Date of Bulletin: JUL 03, 2001

NHTSA Item Number: 623659

Component: INTERIOR LIGHTING

Summary:

CUSTOMERS MAY COMPLAIN OF 4-WHEEL DRIVE LIGHT ILLUMINATING.\*JB

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 010846002

Date of Bulletin: JUL 01, 2001

NHTSA Item Number: 620818

Component: EQUIPMENT:ELECTRICAL:NAVIGATIONAL SYSTEM(GLOBAL POSITIONING SYSTEM)

Summary:

INFORMATION ON PROGRAMMING OF REPLACEMENT ONSTAR VEHICLE COMMUNICATION AND INTERFACE MODULES (VCIM). \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

**For TrailVoy.com Members Only**

**For TrailVoy.com Members Only**

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : DCS760

Date of Bulletin: JUN 22, 2001

NHTSA Item Number: 623467

Component: ENGINE AND ENGINE COOLING:ENGINE:GASOLINE

Summary:

INFORMATION REGARDING LL8 ENGINE LABOR OPERATIONS. \*SLC

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : DCS760

Date of Bulletin: JUN 22, 2001

NHTSA Item Number: 623467

Component: OTHER

Summary:

INFORMATION REGARDING LL8 ENGINE LABOR OPERATIONS. \*SLC

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 070601

Date of Bulletin: JUN 07, 2001

NHTSA Item Number: 623827

Component: OTHER

Summary:

INFORMATION REGARDING ROOF MOUNTED LUGGAGE CARRIER BOW POSITIONING. \*SLC

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 010601017

Date of Bulletin: JUN 01, 2001

NHTSA Item Number: 623214

Component: OTHER

Summary:

INFORMATION REGARDING FLYWHEEL HOLDING TOOL J 44226-3A MODIFICATION OR REPLACEMENT. \*YH

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 01034

Date of Bulletin: MAY 14, 2001

NHTSA Item Number: 619729

Component: SUSPENSION:FRONT:CONTROL ARM

Summary:

CAMPAIGN INFORMATION TO REPLACE THE LEFT AND THE RIGHT FRONT LOWER CONTROL ARM BRACKETS. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

**For TrailVoy.com Members Only**

**For TrailVoy.com Members Only**

Service Bulletin Num : 10501

Date of Bulletin: MAY 10, 2001

NHTSA Item Number: 619777

Component: POWER TRAIN:AUTOMATIC TRANSMISSION

Summary:

THIS MESSAGE APPLIES TO A POSSIBLE DELAYED ENGAGEMENT OF THE TRANSMISSION THAT MAY OCCUR AFTER THE VEHICLE SITS FOR TWO TO THREE WEEKS. \*T

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 120401

Date of Bulletin: APR 12, 2001

NHTSA Item Number: 619412

Component: POWER TRAIN:AXLE ASSEMBLY

Summary:

SUBJECT REGARDING EXCHANGE PROGRAM, BULLETIN NUMBER 010420003 IMPLEMENTED FOR THE 2002 EIGHT INCH RING GEAR AXLE. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 080401

Date of Bulletin: APR 08, 2001

NHTSA Item Number: 619407

Component: SEAT BELTS

Summary:

INFORMATION ON USING THE SEAT AND SHOULD BELT EXTENDERS. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 010730018

Date of Bulletin: APR 01, 2001

NHTSA Item Number: 619710

Component: POWER TRAIN:AUTOMATIC TRANSMISSION:CONTROL MODULE (TCM, PCM)

Summary:

SUBJECT REGARDING TECH 2 INFORMATION ON 4L60-E SHIFT ADAPTS. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 33

Date of Bulletin: MAR 01, 2001

NHTSA Item Number: 619223

Component: STRUCTURE:BODY

Summary:

INFORMATION ON HEADLINER REPLACEMENT, HEADLINER HARNESS ROUTING, AND REPLACING OR SERVICING THE SUNROOF ON VARIOUS MODELS INCLUDING THE 2002 CHEVROLET TRAILBLAZER. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

**For TrailVoy.com Members Only**

**For TrailVoy.com Members Only**

Service Bulletin Num : 010420003

Date of Bulletin: MAR 01, 2001

NHTSA Item Number: 622986

Component: POWER TRAIN:AXLE ASSEMBLY

Summary:

SUBJECT REGARDING REAR AXLE EXCHANGE PROGRAM. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 3077

Date of Bulletin: JAN 01, 1901

NHTSA Item Number: 10009677

Component: ENGINE AND ENGINE COOLING:COOLING SYSTEM:FAN

Summary:

TICK NOISE AT IDLE. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 3110A

Date of Bulletin: JAN 01, 1901

NHTSA Item Number: 10010201

Component: VISIBILITY:WINDSHIELD WIPER/WASHER:MOTOR

Summary:

WASHER MOTOR FOR THE FRONT WIPERS CONTINUOUSLY RUNS WHILE THE KEY ON. \*SC UPDATE. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 3154

Date of Bulletin: JAN 01, 1901

NHTSA Item Number: 10010285

Component: ENGINE AND ENGINE COOLING:ENGINE

Summary:

MISFIRE, BUMP OR MULTIPLE BUMPS AFTER A 1-2 UPSHIFT. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 3050

Date of Bulletin: JAN 01, 1901

NHTSA Item Number: 10010366

Component: POWER TRAIN

Summary:

POP OR SNAP NOISE FROM THE REAR OF THE VEHICLE DURING AGGRESSIVE ACCELERATION OR DECELERATION MANEUVERS. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 3150

Date of Bulletin: JAN 01, 1901

**For TrailVoy.com Members Only**

**For TrailVoy.com Members Only**

NHTSA Item Number: 10010547

Component: ENGINE AND ENGINE COOLING

Summary:

CYLINDER LINER REPLACEMENT INFORMATION - INLINE TRUCK ENGINES. \*EH

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 3177

Date of Bulletin: JAN 01, 1901

NHTSA Item Number: 10010599

Component: POWER TRAIN:AXLE ASSEMBLY

Summary:

REPEAT FRONT AXLE FLUID LEAK. \*EH

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 3208

Date of Bulletin: JAN 01, 1901

NHTSA Item Number: 10010607

Component: FUEL SYSTEM, OTHER:STORAGE:FUEL GAUGE SYSTEM

Summary:

4WD INOPERATIVE AND OR ERRATIC FUEL GAUGE AND OR DIAGNOSTIC TROUBLE CODE'S. \*EH

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 3216

Date of Bulletin: JAN 01, 1901

NHTSA Item Number: 10010618

Component: ELECTRICAL SYSTEM:IGNITION

Summary:

ERRATIC OPERATION OF PERSONALIZATION WITH IGNITION CYCLE. \*EH

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 3222

Date of Bulletin: JAN 01, 1901

NHTSA Item Number: 10010630

Component: POWER TRAIN

Summary:

INTERMITTENT BOOM, RUMBLING NOISE AT HIGHWAY SPEED. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 3061B

Date of Bulletin: JAN 01, 1901

NHTSA Item Number: 10010634

Component: ELECTRICAL SYSTEM

**For TrailVoy.com Members Only**





**For TrailVoy.com Members Only**

Summary:

MISFIRE AT IDLE COLD AND POSSIBLE P0171 AND OR P0174. \*EH

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 3274

Date of Bulletin: JAN 01, 1901

NHTSA Item Number: 10011719

Component: STEERING

Summary:

INSTALLATION OF A POWER STEERING HOSE TO A NEW STEERING GEAR. \*EH

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 3280

Date of Bulletin: JAN 01, 1901

NHTSA Item Number: 10011760

Component: STEERING

Summary:

STEERING NOISE WHEN TURNING. THIS SERVICE BULLETIN SUPPLEMENTS 040232007. \*EH

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 3209

Date of Bulletin: JAN 01, 1901

NHTSA Item Number: 10011817

Component: ENGINE AND ENGINE COOLING:EXHAUST SYSTEM

Summary:

EXHAUST MOAN AT IDLE OR PARKING LOT MANEUVERS. \*EH

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 3138

Date of Bulletin: JAN 01, 1901

NHTSA Item Number: 10011821

Component: POWER TRAIN

Summary:

REDUCED POWER LIGHT ON AND DIAGNOSTIC TROUBLE CODE P1680 P1221 AND OR P1271 STORED IN THE POWERTRAIN CONTROL MODULE. \*EH

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 3285

Date of Bulletin: JAN 01, 1901

NHTSA Item Number: 10013373

Component: ENGINE AND ENGINE COOLING:ENGINE



## For TrailVoy.com Members Only

Summary:

UNABLE TO ACHIEVE ALIGNMENT SPECIFICATIONS AFTER CAMPAIGN 01034. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 3373

Date of Bulletin: JAN 01, 1901

NHTSA Item Number: 10013523

Component: AIR BAGS

Summary:

SIR LIGHT ON STEADY AFTER BULB TEST AND NO DIAGNOSTIC TROUBLE CODES (DTCS). \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 3300

Date of Bulletin: JAN 01, 1901

NHTSA Item Number: 10013572

Component: POWER TRAIN:DRIVELINE

Summary:

NOISE VIBRATION ON DRY PAVEMENT. \*EH

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 3351

Date of Bulletin: JAN 01, 1901

NHTSA Item Number: 10014853

Component: POWER TRAIN:TRANSFER CASE (4-WHEEL DRIVE)

Summary:

INTERMITTENT MALFUNCTION INDICATOR LAMP (MIL) WITH DIAGNOSTIC TROUBLE CODE (DTC) C0374 OR ERRATIC 4WD/AWD OPERATION. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 3232

Date of Bulletin: JAN 01, 1901

NHTSA Item Number: 10014870

Component: ENGINE AND ENGINE COOLING:ENGINE

Summary:

1999 - 2005 GEN II COLD ENGINE MISFIRE AT IDLE WITH POSSIBLE P0171 AND/OR P0174. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 3680

Date of Bulletin: JAN 01, 1901

NHTSA Item Number: 10016544

Component: EXTERIOR LIGHTING:HEADLIGHTS

Summary:

AUTOMATIC HEADLAMP DEFEAT INOPERATIVE AFTER BCM REPLACEMENT. \*TT

## For TrailVoy.com Members Only

**For TrailVoy.com Members Only**

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 3420A                      Date of Bulletin: JAN 01, 1901  
NHTSA Item Number: 10017010  
Component: POWER TRAIN  
Summary:  
PING, POP OR CLICK NOISE FROM UNDER THE REAR. \*SC

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 3656                      Date of Bulletin: JAN 01, 1901  
NHTSA Item Number: 10017014  
Component: VISIBILITY:DEFROSTER/DEFOGGER SYSTEM:WINDSHIELD:BLOWER  
Summary:  
REPEAT REAR BLOWER MOTOR FAILURE OR INOPERATIVE. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 3405                      Date of Bulletin: JAN 01, 1901  
NHTSA Item Number: 10017130  
Component: ENGINE AND ENGINE COOLING:ENGINE  
Summary:  
ENGINE IS HARD TO START AFTER FILLING THE FUEL TANK. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 3577                      Date of Bulletin: JAN 01, 1901  
NHTSA Item Number: 10017158  
Component: ELECTRICAL SYSTEM:STARTER ASSEMBLY:RELAY  
Summary:  
NO CRANK NO START NO DIAGNOSTIC TROUBLE CODES. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002  
Manufacturer : GENERAL MOTORS CORP.  
Service Bulletin Num : 3335                      Date of Bulletin: JAN 01, 1901  
NHTSA Item Number: 10017179  
Component: EXTERIOR LIGHTING:TAIL LIGHTS  
Summary:  
SUPPLEMENT TO CAMPAIGN 04087 / SCREWS BREAK IN THE TAIL LAMP HOUSING. \*SC

---

Make : CHEVROLET                      Model : TRAILBLAZER                      Year : 2002

**For TrailVoy.com Members Only**

## For TrailVoy.com Members Only

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 00773

Date of Bulletin: JAN 01, 1901

NHTSA Item Number: 10017190

Component: POWER TRAIN

Summary:

4L60E, 4L65E REPLACEMENT VALVE BODY GASKETS DOES NOT SEEM TO FIT. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 3110C

Date of Bulletin: JAN 01, 1901

NHTSA Item Number: 10017249

Component: VISIBILITY:WINDSHIELD WIPER/WASHER

Summary:

WIPER/WASHER WILL NOT SHUT OFF OR OTHER POSSIBLE ISSUES. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 3516

Date of Bulletin: JAN 01, 1901

NHTSA Item Number: 10017393

Component: POWER TRAIN:AUTOMATIC TRANSMISSION

Summary:

VIBRATION FELT AND HEARD AT LOW RPM DURING PARKING LOT MANEUVERS. \*TT

---

## 2002 TrailBlazer EXT

Make : CHEVROLET

Model : TRAILBLAZER EXT

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 020526001B

Date of Bulletin: JAN 01, 2005

NHTSA Item Number: 10006115

Component: SERVICE BRAKES, AIR

Summary:

REAR PARKING BRAKE SHOE RETAINING SPRING CLIP SERVICE KIT FOR DRUM-IN-HAT (DIH) EQUIPPED VEHICLES. \*TT UPDATE. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER EXT

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 3152

Date of Bulletin: DEC 01, 2004

NHTSA Item Number: 10009989

Component: EQUIPMENT:ELECTRICAL:AIR CONDITIONER

For TrailVoy.com Members Only

## For TrailVoy.com Members Only

Summary:

BLOWER SPEED CHANGES ON ITS OWN. \*TC UPDATE. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER EXT

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 04017A

Date of Bulletin: SEP 29, 2004

NHTSA Item Number: 10010181

Component: EXTERIOR LIGHTING:TAIL LIGHTS

Summary:

TAIL LAMP/STOP LAMP(S) MAY BECOME INOPERATIVE. GM ADMINISTRATIVE MESSAGE. \*NM

---

Make : CHEVROLET

Model : TRAILBLAZER EXT

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 040845010

Date of Bulletin: SEP 01, 2004

NHTSA Item Number: 10011074

Component: ELECTRICAL SYSTEM

Summary:

VARIOUS INTERIOR ELECTRICAL CONCERNS, IP GAUGES/LIGHTING INOPERATIVE, HVAC CONTROLS INOPERATIVE, BLOWER MOTOR INOPERATIVE, RADIO INOPERATIVE, FLASHER INOPERATIVE. \*TT

---

Make : CHEVROLET

Model : TRAILBLAZER EXT

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 01900

Date of Bulletin: JAN 01, 2004

NHTSA Item Number: 10006472

Component: ELECTRICAL SYSTEM:FUSES AND CIRCUIT BREAKERS

Summary:

UNDER HOOD FUSE BLOCK - 125 AMP MEGA FUSE BLOWN. ALSO INCLUDING BUICK RAINIER 2002, 2003.  
\*MR

---

Make : CHEVROLET

Model : TRAILBLAZER EXT

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 01676

Date of Bulletin: JAN 01, 2004

NHTSA Item Number: 10007188

Component: ENGINE AND ENGINE COOLING:COOLING SYSTEM:FAN

Summary:

4.2 4L60E ENGINE COOLING FAN CONTACTS SHROUD AFTER REPLACING RADIATOR. \*MR

---

Make : CHEVROLET

Model : TRAILBLAZER EXT

Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 02023

Date of Bulletin: JAN 01, 2004

NHTSA Item Number: 10007212

Component: ENGINE AND ENGINE COOLING:ENGINE

**For TrailVoy.com Members Only**

Summary:

INTERMITTENT NO CRANK NO START. SECURITY LIGHT MAY BE ON OR OFF. 4.2 LL8 ENGINE. \*NM

---

Make : CHEVROLET                      Model : TRAILBLAZER EXT                      Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 3151

Date of Bulletin: JAN 01, 2004

NHTSA Item Number: 10009986

Component: VISIBILITY:REARVIEW MIRRORS/DEVICES:INTERIOR

Summary:

INSIDE REAR VIEW MIRROR DOES NOT DISPLAY AMBIENT TEMPERATURE WITH CJ2 OPTION. \*TC

---

Make : CHEVROLET                      Model : TRAILBLAZER EXT                      Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 030866008

Date of Bulletin: AUG 01, 2003

NHTSA Item Number: 10012578

Component: STRUCTURE:BODY

Summary:

PERIMETER SEAL/GASKET PULLS AWAY FROM LICENSE PLATE HOUSING AND/OR EXCESSIVE ADHESIVE AROUND GASKET. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER EXT                      Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 3110A

Date of Bulletin: JAN 01, 1901

NHTSA Item Number: 10010201

Component: VISIBILITY:WINDSHIELD WIPER/WASHER:MOTOR

Summary:

WASHER MOTOR FOR THE FRONT WIPERS CONTINUOUSLY RUNS WHILE THE KEY ON. \*SC UPDATE. \*TT

---

Make : CHEVROLET                      Model : TRAILBLAZER EXT                      Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 3253

Date of Bulletin: JAN 01, 1901

NHTSA Item Number: 10011614

Component: ELECTRICAL SYSTEM

Summary:

ANTI BRAKES SYSTEM BRAKE LIGHT AND OR SERVICE BRAKE MESSAGE WITH DIAGNOSTIC TROUBLE CODE C0238. \*EH

---

Make : CHEVROLET                      Model : TRAILBLAZER EXT                      Year : 2002

Manufacturer : GENERAL MOTORS CORP.

Service Bulletin Num : 3335

Date of Bulletin: JAN 01, 1901

NHTSA Item Number: 10017179

Component: EXTERIOR LIGHTING:TAIL LIGHTS

**For TrailVoy.com Members Only**

**For TrailVoy.com Members Only**

Summary:

SUPPLEMENT TO CAMPAIGN 04087 / SCREWS BREAK IN THE TAIL LAMP HOUSING. \*SC

---

**For TrailVoy.com Members Only**